


RON



PLAN VIEW



SECTION VIEW



TRENCH DETAIL

NOTES:

- INSTALL ANODE IN NATIVE SOIL. DO NOT BACKFILL ANODE WITH SAND OR STONE.
- 2. DO NOT THERMITE WELD TO PVC PIPE.

- 1. ANODE LEAD WIRE AND TEST WIRE TO BE THERMITE WELDED TO CONNECTOR PLATE PRIOR TO ATTACHING CONNECTOR PLATE TO DUCTILE IRON SERVICE SADDLE.
- 2. ANODES PLACED AT SAME DEPTH AS THE BOTTOM OF PIPE AND AT A MINIMUM OF 18" FROM EDGE OF PIPE, SEE TRENCH DETAIL.
- REMOVE COATING FROM DUCTILE IRON SERVICE SADDLE WHERE CONNECTOR PLATE IS TO BE MOUNTED. REMOVE COATING IMMEDIATELY PRIOR TO ATTACHING THE CONNECTOR PLATE.
- DO NOT THERMITE WELD TO PVC PIPE.
- ATTACH TEST WIRE TO SERVICE TUBING WITH 2" DUCT TAPE NEAR CORPORATION, YOKE, AND AT 10 FEET INTERVALS. TERMINATE TEST WIRE WITH 24" COILED WIRE ALONG INSIDE OF METER BOX.