



BID OPENING CERTIFICATION RECORD

ublic Body	Address	PBE	PBE -15%	PBE +15%
2401 Ashley Rd		40,300	40,300 34,255	
Bid Results				
Bidder	Contractor	Amount	Projected Start Date	Projected Finish Date
1.	Jasper	50,565	12-11-2023	1/15/2024
2.				
3.				
4.				
5.				
6.				



SAFE HOME

CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

The Bids will be opened at 600 East Trade St. immediately following the above due date and time.

Company Acknowledgen	nent:
The undersigned, having provisions of the housing funded through the Cit fully inspected the site in the time stated and in strany and all labor and materials.	become thoroughly familiar with the terms, conditions, limitations, and ng improvement work to be performed at <u>2104 Ashely Rd</u> to be y of Charlotte Neighborhood & Business Services, in addition, having all particulars, hereby proposes and agrees to fully perform the work within ict accordance with the proposed contract documents including furnishing of terials, and to do all work required to complete said Work in accordance with
the advised respective co	ontractual, for the sum of money:
	rvices and equipment necessary for the completion of the Work shown
on the Drawings and in	The Specifications:
FIFTY THOUSANK	FIVE HUNDER SIXTY-FICK & MOOllars (\$ 50,565,]
Written total	
Specs Dated: 7/11	Number of Pages: 3 pgs (2 writeup,1 floor plan
Addenda # 1 Dated:	Number of Pages:
Addenda # 2 Dated:	Number of Pages:
Project Schedule: Minim	um Start Date - VECEMB4R 11, 2023
Completion Deadline:	TANUARY 19, 2023
<u> </u>	,

Please Print and Sign:	
Company Name/Firm:	
1	Jasper Environmental Services, Inc
Authorized Representative Name:	Thaddeus Kuzniar
Signature:	Date:
	September 7, 2023

Work Specification

Prepared By:
City of Charlotte Housing & Neighborhood Services
600 E. Trade Street
Charlotte, NC 28202
(704) 336-7600

Property Details				Branches Personal Verson	
Address:	2104 Ashley Rd)wner:	Serima Killian	- All Billion (1995) (1995) All Commission (1995) (1995) (1995) (1995)
ridarood.	Charlotte, NC 28208		wner Phone:	Cell: (980) 319-6	876
Structure Type:			rogram(s):	Tested- HAS LEA	
Square Feet:		•		LeadSafe 2019	
Year Built:				Healthy Homes L HPP FY22 (West	
Property Value:				111 1 122 (West	erry rima)
Tax Parcel:					S.
Census Tract:					
Property Zone:					E .
	NASS BERMININA SAMBAR A COMPENSA SAMBAR SA SA		No. 3 (10 (10 (10 (10 (10 (10 (10 (10 (10 (10	i contre della vend en promotes della c	nganananananananananananananananananana
Repairs					
<u>Description</u>				Floor Room	Exterior
All Contractor's Project	ct Requirements		4	GENERA	L REQUIREMENTS
The contractor is respon	nsible for all project requirements, inclu	iding but not	imited to:		1
Obtaining all permits red	quired. Said permits shall include all ite	ems in this sc	ope of work.		
Provide temporary toilet	facilities from job start until the comple	etion of work.			
Provide AS MANY roll-	off dumpsters as needed without dama	aina tha cita	Collect constru	uotion debrie using	duet control methode
	i repair any evidence of the dumpster ι		Collect collect	iction debns daing	dust control metrious.
Oantinastan mari baril da					
Contractor may naul de	bris away daily using dump trailers or t	rucks.			
					Ŋ.
×				v	= \$ Z,00e, ~
		Bid Cost:	Base	_X Quantity	Total Cost
		·····		Quantity	Total Cost
See Attached Lead Sc	ope			GENERA	L REQUIREMENTS
	ned in accordance with applicable regu				
	opriate. Mecklenburg County requires nitting under general conducts.	bullaing pern	iits for Lead Ha	azaro Reduction in	the work involves
	- •		94 30	5 2	سه أرجة والإرواب
		Bid Cost:		_X	= \$41,710°=
			Base	Quantity	Total Cost

Work Specification

HH - Vinyl Window

EXTERIOR

Exterio

Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW- E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass.

***Only WOODEN windows are to be replaced. Cost of wrapping framing components (casing, sill, header) is to be included in the LEAD scope of work. This means that the total cost of these window replacements is split between this line item, and the lead scope. ***Window count is for (4) windows.



Bid Cost: #600 x 4 = #2400, **

Base Quantity Total Cost

HH - Seamless Aluminum Gutter & Downspouts - Install

EXTERIOR

Exterior

Install K- type .026 gauge seamless aluminum gutter to service roof with sufficient pitch to downspouts. White or brown color choice by owner.



Bid Cost: X = #Z/675, Garage Base Quantity Total Cost

HH - Screen Repair and Replace

EXTERIOR

Exterior

Replace exterior screens on front screened-in porch to provide securely attached screens to keep out any animals, pests or other debris.



Bid Cost: $X = \frac{$1/780^{-4}}{}$ Base Quantity Total Cost

Certification

Contractor Name:

Jasper Environmental Services, Inc.

Total Cost:

\$50,565

Signature:

Date:

September 7, 2023

Scope of Work for Lead Hazard Control

Address:	2104 Ashley Ro	Date:	8/22	/2023	}	
			— '	•		

All work described must be performed by a North Carolina state certified lead firm and a state lead permit is required. All work must comply with all applicable federal, state, and local regulations. Provide a separate price for each line item and add the total of line items at the end of the scope. Transfer the lead scope total to the lead control line item in the main scope of work.

Lead Hazard (from LIRA)	Method of Control and Scope of Work	Number	Unit Cost	Line Item Cost
Side A through Side D – gray wood walls and white wood corner boards (some of the wood has been randomly replaced with wood not coated with lead-based paint)	Cover wood with Tyvek and aluminum or vinyl			\$16,750

Side A through Side D — white wood fascia, soffits, rafters, trim boards and attic air vents and frames (some of the fascia boards have been randomly replaced with wood not coated with lead-based paint). (NOTE: The carport components are not coated with lead-based paint, HOWEVER the house rafters, soffits and trim under the carport ceiling at the carport/house attachment points are coated with lead-based	Cover with Tyvek and aluminum or vinyl. (NOTE: work includes removing existing gutters and downspouts. New gutters and downspouts to be installed on the Healthy Homes scope of work.)			
paint)			= 14	\$7,275,
Side A through Side D – gray brick foundation on original house	Scrape loose paint and re-paint			\$1,450.
Side B – gray brick chimney	Scrape loose paint and re-paint			\$875.
Window A1, B3, D4 through D6 – white wood window casings, headers and sill	Cover with Tyvek and aluminum or vinyl. (NOTE: windows to be replaced on the Healthy Homes scope of work. This line item is for wrapping the trim components ONLY).	4	\$300°	\$1200,"


Window B1 and B2 – white wood header	Cover with Tyvek and aluminum or vinyl	Z	#300°	\$600,0
Window B4 and B5 – white wood shutters	Remove	11 (V. 12/200)		\$100,0
Side A through Side D – paint chips along drip line and elevated lead soil level	Remove drip line soil approximately 4" deep and extending from the foundation out approximately three feet and install new soil with lead levels below 200 ppm			\$5,560
Room 1 – Side C – gray wood wall	Cover with Tyvek and aluminum or vinyl (unheated room) (NOTE: include in overall vinyl siding price – the first line item on this scope)	-	-	# O, ~
Room 1 – Side A, B and D – whte wood ceiling support beams and trim boards	Cover with Tyvek and aluminum or vinyl (include any work necessary to un-install/re-install or replace screening for screened-in porch)	F ,		\$/,650,0
Room 1 – Window C1 and C2 – white wood window casings, headers and sills	Cover with Tyvek and aluminum. (NOTE: windows to be replaced on the Healthy Homes scope of work. This line item is for wrapping the trim components ONLY).	Z	#350,°	\$ 700.9
Room 1 – Door C1 – white wood door casings, header, jambs and stops and gray/brown wood threshold	Replace door jambs, stops and threshold with a pre- hung door unit. Wrap any remaining elements in Tyvek and aluminum		er y	\$ 1,750.

Room 5 – Side A and B – gray wood walls and trim boards (former exterior components)	Cover with wallboard, wood panel or vinyl. (NOTE: any newly installed material shall be either prefinished or prepped and painted Owner's choice of color)	# 21800°
Throughout – elevated lead dust levels	Complete specialized cleaning throughout house	\$1,500

Total Bid for Lead Scope: \$

\$41,710,00

SIDEB



Legend

= Window ---- = Door

= Soil Sample Location

NOT TO SCALE